DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003702

Address: 333 Burma Road **Date Inspected:** 02-Aug-2008

City: Oakland, CA 94607

OSM Arrival Time: 1400 **Project Name:** SAS Superstructure **OSM Departure Time:** 2300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name: Chen Xi **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** OBG

Summary of Items Observed:

Tower Shop Bay 3 Deck Panel repairs

The QA Inspector randomly observed ZPMC personnel performing grinding of repairs for the Orthotropic Box Girder (OBG) deck panel Partial Joint Penetration (PJP) welds. During initial observations it was noted that twenty-six (26 ea) deck panels are inside the shop. This QA inspector observed ZPMC performing repair's on the following deck panels; DP217-001, DP243-001, DP325-001, DP082-001 and DP325-002 these were in process for the remainder of this shift. This QA inspector along with ZPMC and ABF performed the 3 party initial visual inspections on DP379-001 and agreed on the locations for repair. This QA inspector was also informed of final inspection needed for deck panels DP189-001, DP218-001 and DP434-001 which was performed along with ZPMC and ABF and agreed that the repairs appeared to be within compliance. Certified Welding Inspector for ZPMC Chen Xi was present at this location for the monitoring of the deck repairs and inspection. Also noted in bay 3 to monitor deck panel repairs were ABF personnel Kevin Chen, Wang Zhong Yuan and Ding Bao Hua.

Summary of Conversations:

As Noted above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco, 1-381-694-2685, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Riley,Ken Quality Assurance Inspector

Reviewed By: Carreon, Albert QA Reviewer